

TO BE FILLED BY THE INSPECTING OFFICER
(Assistant Engineer)

ST. ANNE'S PUBLIC SCHOOL, KOOVAPPADY

1 Name of the Officer **Eldho Thomas**
Assistant Engineer

2 Location **Koovappady GP**

3 Period for which the Certificate is issued **2023-24**

4 Types of building **Details of Building:-**

5 Nature of defect if any **RCC Roof**

a) Foundation and basement	}	GF	6.26 x 6.36 x 3.30 (1 Classroom)
b) Superstructure		12.79 x 6.18 x 3.30 (Lab)	
c) Doors & Windows		6.08 x 6.08 x 3.30 (5 Classroom)	
d) Wood work wrought and put up.		6.08 x 6.18 x 3.30 (Office)	
e) Roof		6.08 x 6.08 x 3.30 (Principal room)	
f) Flooring		4.38 x 3.00 x 3.30 (Sick room)	
g) Miscellaneous (Craks if any)		FF	6.08 x 6.08 x 3.60 (15 Classroom)
			6.30 x 6.34 x 3.60 (Computer lab)
		Nil	9.50 x 6.20 x 3.60 (Staff room)
			SF
			9.50 x 6.20 x 3.60 (Library)
			6.25 x 6.35 x 3.60 (Staff room)

6 Any major defects notices which will render the building unsafe if any manner **No**

7 Whether maintenance work have been done property. **Yes**

8 Whether the structure is sound or not for Conducting classes **Sound for conducting classes under Normal wind and weather condition.**

Note:-



- 1 The Stability of the structure should be examined also with referance to location altitude intensity of wind exposure to flood etc.
- 2 Any additional observation if deemed necessary for the certificate may be furnished separately with the Certificate.

CERTIFICATE

Certificate that the School was inspected by me on 03.05.2023 and found to be **Fit/Unfit** for conducting classes upto 31.03.2024

Challan No.: KL031683538202223M dated: 28.03.2023

Place **Koovappady**
Date **03.05.2023**



ELDHO THOMAS
PEN - 846117
ASSISTANT ENGINEER
GOVERNMENT